Governors' Health & Safety Walk: June 2016

What did we do?

The School Business Manager led us round the school allowing us to have a real honest 'warts and all' view. We visited all areas of the school and grounds and looked at not only health and safety but also asset management. We compiled the following actions:

Area	Action Required	Associated Risk	Comments	Date
Hall	Stage storage	Unsightly	SBM to look into	
		Fall hazard	different storage	
			units for stage.	
Hall	Missing Skirting	Unsightly	Caretaker	
	Board		informed.	
Y6 Classroom	Scooter blocking	Fire route	Remove ASAP	Competed June
	Fire door	blocked		2016
ICT Suite	Untidy	No risk but	SBM will be	2017/18 and
		better use of	looking into	ongoing
		space	creation of a	
			real learning	
			resource centre.	
			Consideration	
			as part of financial	
			planning	
			2017/18	
Nursery	Electric cover on	Risk of		
rtaroory				
		o.ooooa.or	· ·····otcar	
	wire			
	Nursery Kitchen	No risk but		
	units need	unsightly	2017/18 budget	
	refurbishment		consideration	
	Secondary	Current point is		
			with SLT	
	for Nursery			
Main tailata	Doop alcon		Clooning to be	Cummor 2046
iviain tollets		nygierie/Smeii	•	
			•	
	•			· •
				pianing 2017.
	`			
Nursery Main toilets	Nursery Kitchen units need refurbishment	unsightly	Job raised with Hillstar 2017/18 budget	Summer 2016 and consider as part of financial planning 2017.

		T		T
			maternity leave for 2016/17	
Chairs in corridors	Legs protrude	Trip hazard	SBM to log any issues arising from this.	Ongoing.
Mugs in classroom	Untidy, to be removed. Only to be taken down to classrooms out of school hours.	Risk of scalding if in classroom when children present, also unsightly.		
Top Yard	Fence required on top yard to fence off resident's access.	Security	SBM to get quotes for installation. To form part of budget considerations 2017/18.	2017/18
Colour of Classrooms doors into corridor.	Could these be painted dark blue to link with school colours?	No risk, asset management.	SBM to get quotes. Will look to address Summer 2017	Summer 2017
Year 3 sink	Look to replace	Unsightly, of a poor standard.	SBM to get quote.	
Ash Sapling in EYFS play area	To be removed due to rate of growth.	To be removed due to rate of growth.	SBM to organise grounds maintenance	Work organised Nov 2016.
Walls Top Yard	Relatively poor condition due to trees protruding	Risk of wall collapse	SBM to speak to land registry re ownership and look to rectify.	
School Sign	Apostrophe in wrong place	No risk, Asset management	SBM to rectify. New sign will be ordered.	
Water Butts	Can they be positioned to run into gardening club	No risk but improved use of resources	SBM to discuss options with grounds maintenance.	
Health & Safety checks to plot into committees for review.			SBM and CB to address cycle of review.	
General condition of school				